

# General Environmental Incident Summary

**Incident:** 3771      **Date/Time Notice:** 6/2/2015      1600      **DEM Incident No:**  
**Responsible Party:** Secure Energy Services  
**Date Incident:** 6/2/2015      **Time Incident:** 1500      **Duration:** 30 minutes  
**County:** Williams      **Twp:** 157      **Rng:** 101      **Sec:** 36      **Qtr:** SE  
**Lat:** 48.37332      **Long:** -103.66910      **Method:** Derived from Twn Rng  
**Location Description:** Secure Energy 13 Mile Special Waste Landfill  
14 miles north of Williston, 2 miles west of Highway 85  
Mailing address: 13809 66th Street NW  
**Submitted By:** Vicki Manzo      **Affiliation:** Secure Energy  
**Address:** 5807 Front Street West  
**City:** Williston      **State:** ND      **Zip:** 58801

## Received By:

**Contact Person:** Melissa Gibb  
5807 Front Street West  
Williston, ND 58801

**Distance Nearest Occupied Building:** 0.75 Miles      **Release Contained:** Yes

**Type of Incident:** leachate overflow from cell

**Description of Released Contaminant:** landfill leachate

**Volume Spilled:** 50.00 gallons      **Ag Related:** No

**EPA Extremely Hazardous Substance:** No      **Reported to NRC:** No

## Cause of Incident:

It has been raining heavily, and there was some leachate ponding on the surface of the cell prior to the rainfall.

## Risk Evaluation:

No immediate risks.

**# of Fatalities:**      **# of Injuries:**      **Affected Medium:** 04 - water and soil

## Potential Environmental Impacts:

Some of the leachate may have soaked into the ground, and may reach the groundwater table. This will be evaluated. In addition, the leachate may have affected the quality of the water in the surface water pond. This will also be evaluated.

## Action Taken or Planned:

The leachate has reached the stormwater pond. The operators are working at hooking up a trash pump and directing the leachate to the surface impoundment. In the meantime, the County has given Secure permission to run 2 trucks out to the site, for 6-7 hours to pump leachate. The Operations group is reviewing the Plan of Operations to ensure procedures are being followed, and will come up with corrective actions to ensure that leachate is not ponding in the cell, and cannot overflow the berm. The stormwater pond will be sampled to ensure that no contaminants are released from it. The pond has over 4' of freeboard, currently, so there is no danger of overflow.

**Wastes Disposal Location:** Down hole at the Secure 13 Mile FST.

**Agencies Involved:**

### **Updates**

---

**Date:** 6/3/2015      **Status:** Reviewed - Assigned to NDDoH Division

**Author:** Crowdus, Kory

**Updated Volume:**

**Notes:**

Release occurred at a special waste landfill. Report forwarded to Division of Waste Management.